

# ARINC Standard – Errata Report

## 1. Document Title

**ARINC Specification 818:** *Avionics Digital Video Bus, High Data Rate - Uncompressed*  
Published: December 19, 2006

## 2. Reference

Page Number: 33 Section Number: 3.2.7 Date of Submission: 8MAR07

## 3. Error

ARINC 818 Table 14:

Type	The Type code field may be set to 60h (FC-AV) for legacy installations. (Note: Future Supplement 1 may define a new Type Code for ADVB, pending assignment by ANSI.)
------	---

## 4. Recommended Correction

ARINC 818 Table 14:

Type	The Type code field shall be set to 61h for ADVB implementations. Note: Type code 60h (FC-AV) was specified in the first release of this standard pending assignment of a dedicated Type code by ANSI. Type code 60h may be encountered in legacy implementations.
------	---

## 5. Reason for Correction

First release of ARINC 818 contained Type Code for FC-AV (60h). This errata announces ANSI designation of Type Code ADVB (61h) dedicated to ARINC 818.

## 6. Submitter (Optional)

Digital Video Subcommittee